



PHOTO # 1

Official Environmental Protection Agency Photograph

Subject: Chromium contaminated material that was stored in the steam building

Location: Prairie, Monroe County, Mississippi

TDD#: 04-9010-0049
 Date/Time: 27 October 1988/1500 hours
 Photographer: Eddy Bouzeid
 Witness: Waymon Thompson
 Film: 35 mm / 100 ASA
 Location of Negative: Region 41 - Memphis TAT Office



PHOTO # 2

Official Environmental Protection Agency Photograph

Subject: Contaminated material being excavated from the filled disposal lagoon

Location: Prairie, Monroe County, Mississippi

TDD#: 04-9010-0049
 Date/Time: 22 March 1989/1000 hours
 Photographer: Eddy Bouzeid
 Witness: Waymon Thompson
 Film: 35 mm / 100 ASA
 Location of Negative: Region 41 - Memphis TAT Office

104104

17 4 0002



PHOTO # 3

Official Environmental Protection Agency Photograph

Subject: Excavation of the filled disposal lagoon

Location: Prairie, Monroe County, Mississippi

TDD#: 04-9010-0049
Date/Time: 23 March 1989/1400 hours
Photographer: Eddy Bouzeid
Witness: Waymon Thompson
Film: 35 mm / 100 ASA
Location of Negative: Region 41 - Memphis TAT Office



PHOTO # 4

Official Environmental Protection Agency Photograph

Subject: Excavation in progress

Location: Prairie, Monroe County, Mississippi

TDD#: 04-9010-0049
Date/Time: 24 March 1989/0900 hours
Photographer: Eddy Bouzeid
Witness: Waymon Thompson
Film: 35 mm / 100 ASA
Location of Negative: Region 41 - Memphis TAT Office

17 4 0003



PHOTO # 5

Official Environmental Protection Agency Photograph

Subject: Another view of contaminated material that was buried in the disposal lagoon

Location: Prairie, Monroe County, Mississippi

TDD#: 04-9010-0049
Date/Time: 28 March 1989/1100 hours
Photographer: Eddy Bouzeid
Witness: Waymon Thompson
Film: 35 mm / 100 ASA
Location of Negative: Region 41 - Memphis TAT Office



PHOTO # 6

Official Environmental Protection Agency Photograph

Subject: View of one half of the lagoon that formerly contained cooling water

Location: Prairie, Monroe County, Mississippi

TDD#: 04-9010-0049
Date/Time: 01 October 1990/0900 hours
Photographer: Eddy Bouzeid
Witness: Warren Dixon
Film: 35 mm / 100 ASA
Location of Negative: Region 41 - Memphis TAT Office




PHOTO # 7

Official Environmental Protection Agency Photograph

Subject: Clearing out the site

Location: Prairie, Monroe County, Mississippi

TDD#: 04-9010-0049
 Date/Time: 14 November 1990/0830 hours
 Photographer: Eddy Bouzeid
 Witness: Warren Dixon
 Film: 35 mm / 100 ASA
 Location of Negative: Region 41 - Memphis TAT Office



PHOTO # 8

Official Environmental Protection Agency Photograph

Subject: Sampling of the lagoon's sediment

Location: Prairie, Monroe County, Mississippi

TDD#: 04-9010-0049
 Date/Time: 14 November 1990/1400 hours
 Photographer: Eddy Bouzeid
 Witness: Warren Dixon
 Film: 35 mm / 100 ASA
 Location of Negative: Region 41 - Memphis TAT Office



PHOTO # 9

Official Environmental Protection Agency Photograph

Subject: Trackhoe-215 utilized in the removal activities

Location: Prairie, Monroe County, Mississippi

TDD#: 04-9010-0049
 Date/Time: 26 November 1990/1405 hours
 Photographer: Eddy Bouzeid
 Witness: Kent Kinsinger
 Film: 35 mm / 100 ASA
 Location of Negative: Region 41 - Memphis TAT Office



PHOTO # 10

Official Environmental Protection Agency Photograph

Subject: Loader-953

Location: Prairie, Monroe County, Mississippi

TDD#: 04-9010-0049
 Date/Time: 26 November 1990/1410 hours
 Photographer: Eddy Bouzeid
 Witness: Kent Kinsinger
 Film: 35 mm / 100 ASA
 Location of Negative: Region 41 - Memphis TAT Office



PHOTO # 11

Official Environmental Protection Agency Photograph

Subject: Cement pig

Location: Prairie, Monroe County, Mississippi

TDD#: 04-9010-0049
 Date/Time: 26 November 1990/1415 hours
 Photographer: Eddy Bouzeid
 Witness: Kent Kinsinger
 Film: 35 mm / 100 ASA
 Location of Negative: Region 41 - Memphis TAT Office



PHOTO # 12

Official Environmental Protection Agency Photograph

Subject: Aran unit

Location: Prairie, Monroe County, Mississippi

TDD#: 04-9010-0049
 Date/Time: 26 November 1990/1420 hours
 Photographer: Eddy Bouzeid
 Witness: Kent Kinsinger
 Film: 35 mm / 100 ASA
 Location of Negative: Region 41 - Memphis TAT Office



PHOTO # 13

Official Environmental Protection Agency Photograph

Subject: Power Screen (cutter) utilized to screen and size down material

Location: Prairie, Monroe County, Mississippi

TDD#: 04-9010-0049
Date/Time: 26 November 1990/1425 hours
Photographer: Eddy Bouzeid
Witness: Kent Kinsinger
Film: 35 mm / 100 ASA
Location of Negative: Region 41 - Memphis TAT Office



PHOTO # 14

Official Environmental Protection Agency Photograph

Subject: Dump trucks

Location: Prairie, Monroe County, Mississippi

TDD#: 04-9010-0049
Date/Time: 26 November 1990/1430 hours
Photographer: Eddy Bouzeid
Witness: Kent Kinsinger
Film: 35 mm / 100 ASA
Location of Negative: Region 41 - Memphis TAT Office



PHOTO # 15

Official Environmental Protection Agency Photograph

Subject: Water treatment apparatus being mobilized to the site

Location: Prairie, Monroe County, Mississippi

TDD#: 04-9010-0049
 Date/Time: 04 December 1990/1340 hours
 Photographer: Greg Temple
 Witness: Charlie Stevens
 Film: 35 mm / 100 ASA
 Location of Negative: Region 41 - Memphis TAT Office



PHOTO # 16

Official Environmental Protection Agency Photograph

Subject: Grading the disposal lagoon

Location: Prairie, Monroe County, Mississippi

TDD#: 04-9010-0049
 Date/Time: 08 December 1990/0900 hours
 Photographer: Greg Temple
 Witness: Charlie Stevens
 Film: 35 mm / 100 ASA
 Location of Negative: Region 41 - Memphis TAT Office

174 0009



PHOTO # 17

Official Environmental Protection Agency Photograph

Subject: The disposal lagoon was formed into
a disposal cell

Location: Prairie, Monroe County, Mississippi

TDD#: 04-9010-0049
Date/Time: 08 December 1990/1050 hours
Photographer: Greg Temple
Witness: Kent kinsinger
Film: 35 mm / 100 ASA
Location of Negative: Region 41 - Memphis TAT Office



PHOTO # 18

Official Environmental Protection Agency Photograph

Subject: Installation of the water treatment apparatus

Location: Prairie, Monroe County, Mississippi

TDD#: 04-9010-0049
Date/Time: 11 December 1990/1315 hours
Photographer: Greg Temple
Witness: Kent kinsinger
Film: 35 mm / 100 ASA
Location of Negative: Region 41 - Memphis TAT Office

17 4 0010



PHOTO # 19

Official Environmental Protection Agency Photograph

Subject: Contaminated material removed from the
steam building

Location: Prairie, Monroe County, Mississippi

TDD#: 04-9010-0049
Date/Time: 11 December 1990/1400 hours
Photographer: Greg Temple
Witness: Warren Dixon
Film: 35 mm / 100 ASA
Location of Negative: Region 41 - Memphis TAT Office



PHOTO # 20

Official Environmental Protection Agency Photograph

Subject: Fixation/excavation of the first half of the
lagoon that formerly contained cooling water

Location: Prairie, Monroe County, Mississippi

TDD#: 04-9010-0049
Date/Time: 16 January 1991/0900 hours
Photographer: Toby Blasingame
Witness: Charlie Stevens
Film: 35 mm / 100 ASA
Location of Negative: Region 41 - Memphis TAT Office



PHOTO # 21

Official Environmental Protection Agency Photograph

Subject: Continued fixation/excavation of the lagoon

Location: Prairie, Monroe County, Mississippi

TDD#: 04-9010-0049
Date/Time: 18 January 1991/1400 hours
Photographer: Toby Blasingame
Witness: Charlie Stevens
Film: 35 mm / 100 ASA
Location of Negative: Region 41 - Memphis TAT Office



PHOTO # 22

Official Environmental Protection Agency Photograph

Subject: Fixation/excavation of the second half of the lagoon

Location: Prairie, Monroe County, Mississippi

TDD#: 04-9010-0049
Date/Time: 26 January 1991/1600 hours
Photographer: Toby Blasingame
Witness: Dan Morrow
Film: 35 mm / 100 ASA
Location of Negative: Region 41 - Memphis TAT Office

17 4 0012



PHOTO # 23

Official Environmental Protection Agency Photograph

Subject: Fixation/excavation completed

Location: Prairie, Monroe County, Mississippi

TDD#: 04-9010-0049
Date/Time: 02 February 1991/1500 hours
Photographer: Greg Temple
Witness: Dan Morrow
Film: 35 mm / 100 ASA
Location of Negative: Region 41 - Memphis TAT Office



PHOTO # 24

Official Environmental Protection Agency Photograph

Subject: View of the disposal cells

Location: Prairie, Monroe County, Mississippi

TDD#: 04-9010-0049
Date/Time: 03 February 1991/0900 hours
Photographer: Greg Temple
Witness: Dan Morrow
Film: 35 mm / 100 ASA
Location of Negative: Region 41 - Memphis TAT Office



PHOTO # 25

Official Environmental Protection Agency Photograph

Subject: Dismantling of the steam building

Location: Prairie, Monroe County, Mississippi

TDD#: 04-9010-0049
 Date/Time: 03 March 1991/0800 hours
 Photographer: Greg Temple
 Witness: Dan Morrow
 Film: 35 mm / 100 ASA
 Location of Negative: Region 41 - Memphis TAT Office



PHOTO # 26

Official Environmental Protection Agency Photograph

Subject: View of the water treatment operation

Location: Prairie, Monroe County, Mississippi

TDD#: 04-9010-0049
 Date/Time: 03 March 1991/1630 hours
 Photographer: Greg Temple
 Witness: Dan Morrow
 Film: 35 mm / 100 ASA
 Location of Negative: Region 41 - Memphis TAT Office



PHOTO # 27

Official Environmental Protection Agency Photograph

Subject: View of the decontamination station

Location: Prairie, Monroe County, Mississippi

TDD#: 04-9010-0049
 Date/Time: 04 March 1991/0900 hours
 Photographer: Greg Temple
 Witness: Dan Morrow
 Film: 35 mm / 100 ASA
 Location of Negative: Region 41 - Memphis TAT Office



PHOTO # 28

Official Environmental Protection Agency Photograph

Subject: Dismantling of the water treatment apparatus

Location: Prairie, Monroe County, Mississippi

TDD#: 04-9010-0049
 Date/Time: 04 March 1991/1300 hours
 Photographer: Greg Temple
 Witness: Dan Morrow
 Film: 35 mm / 100 ASA
 Location of Negative: Region 41 - Memphis TAT Office

17 4 0015



PHOTO # 29

Official Environmental Protection Agency Photograph

Subject: Finished torch cutting of the steam building frame

Location: Prairie, Monroe County, Mississippi

TDD#: 04-9010-0049
Date/Time: 05 March 1991/1400 hours
Photographer: Greg Temple
Witness: Dan Morrow
Film: 35 mm / 100 ASA
Location of Negative: Region 41 - Memphis TAT Office



PHOTO # 30

Official Environmental Protection Agency Photograph

Subject: Continued decon of water treatment apparatus

Location: Prairie, Monroe County, Mississippi

TDD#: 04-9010-0049
Date/Time: 05 March 1991/1500 hours
Photographer: Greg Temple
Witness: Dan Morrow
Film: 35 mm / 100 ASA
Location of Negative: Region 41 - Memphis TAT Office



PHOTO # 31

Official Environmental Protection Agency Photograph

Subject: Aeration of the stockpiled material

Location: Prairie, Monroe County, Mississippi

TDD#: 04-9010-0049
 Date/Time: 04 June 1991/1100 hours
 Photographer: Eddy Bouzeid
 Witness: Dan Morrow
 Film: 35 mm / 100 ASA
 Location of Negative: Region 41 - Memphis TAT Office



PHOTO # 32

Official Environmental Protection Agency Photograph

Subject: Excavation of the area between the steam and plating buildings

Location: Prairie, Monroe County, Mississippi

TDD#: 04-9010-0049
 Date/Time: 04 June 1991/1400 hours
 Photographer: Eddy Bouzeid
 Witness: Dan Morrow
 Film: 35 mm / 100 ASA
 Location of Negative: Region 41 - Memphis TAT Office



PHOTO # 33

Official Environmental Protection Agency Photograph

Subject: Excavation of the steam building floor

Location: Prairie, Monroe County, Mississippi

TDD#: 04-9010-0049
 Date/Time: 07 June 1991/0800 hours
 Photographer: Eddy Bouzeid
 Witness: Dan Morrow
 Film: 35 mm / 100 ASA
 Location of Negative: Region 41 - Memphis TAT Office



PHOTO # 34

Official Environmental Protection Agency Photograph

Subject: Another view of the excavation activities between the steam and plating buildings

Location: Prairie, Monroe County, Mississippi

TDD#: 04-9010-0049
 Date/Time: 08 June 1991/1630 hours
 Photographer: Eddy Bouzeid
 Witness: Dan Morrow
 Film: 35 mm / 100 ASA
 Location of Negative: Region 41 - Memphis TAT Office



PHOTO #35

Official Environmental Protection Agency Photograph

Subject: Power grid (shaker) utilized in addition to a
power screen (cutter) in the screening process

Location: Prairie, Monroe County, Mississippi

TDD#: 04-9010-0049
Date/Time: 08 June 1991/1000 hours
Photographer: Eddy Bouzeid
Witness: Dan Morrow
Film: 35 mm / 100 ASA
Location of Negative: Region 41 - Memphis TAT Office

17 4 0019



PHOTO # 36

Official Environmental Protection Agency Photograph

Subject: Screening of the stockpiled material

Location: Prairie, Monroe County, Mississippi

TDD#: 04-9010-0049
Date/Time: 09 June 1991/1530 hours
Photographer: Eddy Bouzeid
Witness: Dan Morrow
Film: 35 mm / 100 ASA
Location of Negative: Region 41 - Memphis TAT Office



PHOTO # 37

Official Environmental Protection Agency Photograph

Subject: Another view of the screening work

Location: Prairie, Monroe County, Mississippi

TDD#: 04-9010-0049
Date/Time: 10 June 1991/1100 hours
Photographer: Eddy Bouzeid
Witness: Dan Morrow
Film: 35 mm / 100 ASA
Location of Negative: Region 41 - Memphis TAT Office



PHOTO # 38

Official Environmental Protection Agency Photograph

Subject: View of the area where the asbestos-containing material was stored

Location: Prairie, Monroe County, Mississippi

TDD#: 04-9010-0049
Date/Time: 11 June 1991/1000 hours
Photographer: Eddy Bouzeid
Witness: Dan Morrow
Film: 35 mm / 100 ASA
Location of Negative: Region 41 - Memphis TAT Office



PHOTO # 39

Official Environmental Protection Agency Photograph

Subject: View of the concrete pumps

Location: Prairie, Monroe County, Mississippi

TDD#: 04-9010-0049
Date/Time: 23 August 1991/0900 hours
Photographer: Ayon Walters
Witness: Warren Dixon
Film: 35 mm / 100 ASA
Location of Negative: Region 41 - Memphis TAT Office



PHOTO #40

Official Environmental Protection Agency Photograph

Subject: Screened material being fed into the Aran
hopper

Location: Prairie, Monroe County, Mississippi

TDD#: 04-9010-0049
Date/Time: 15 August 1991/1330 hours
Photographer: Ayon Walters
Witness: Warren Dixon
Film: 35 mm / 100 ASA
Location of Negative: Region 41 - Memphis TAT Office



PHOTO #41

Official Environmental Protection Agency Photograph

Subject: Panoramic view of the solidified material being
pumped into one of the disposal cells

Location: Prairie, Monroe County, Mississippi

TDD#: 04-9010-0049
Date/Time: 15 August 1991/1400 hours
Photographer: Ayon Walters
Witness: Warren Dixon
Film: 35 mm / 100 ASA
Location of Negative: Region 41 - Memphis TAT Office

17 4 0023



PHOTO #42

Official Environmental Protection Agency Photograph

Subject: Concrete boom truck being utilized in the disposal of the solidified material

Location: Prairie, Monroe County, Mississippi

TDD#: 04-9010-0049
Date/Time: 15 August 1991/1430 hours
Photographer: Ayon Walters
Witness: Warren Dixon
Film: 35 mm / 100 ASA
Location of Negative: Region 41 - Memphis TAT Office

17 4 0024




PHOTO #43

Official Environmental Protection Agency Photograph

Subject: View of the screened material

Location: Prairie, Monroe County, Mississippi

TDD#: 04-9010-0049
Date/Time: 19 August 1991/1400 hours
Photographer: Ayon Walters
Witness: Warren Dixon
Film: 35 mm / 100 ASA
Location of Negative: Region 41 - Memphis TAT Office

17 4 0025



PHOTO #44

Official Environmental Protection Agency Photograph

Subject: Solidification activities in progress

Location: Prairie, Monroe County, Mississippi

TDD#: 04-9010-0049

Date/Time: 19 August 1991/1500 hours

Photographer: Ayon Walters

Witness: Warren Dixon

Film: 35 mm / 100 ASA

Location of Negative: Region 41 - Memphis TAT Office

174 0026



PHOTO #45

Official Environmental Protection Agency Photograph

Subject: The steam building floor after being formed
into a disposal cell

Location: Prairie, Monroe County, Mississippi

TDD#: 04-9010-0049

Date/Time: 20 August 1991/1000 hours

Photographer: Ayon Walters

Witness: Warren Dixon

Film: 35 mm / 100 ASA

Location of Negative: Region 41 - Memphis TAT Office

17 4 0027



PHOTO #46

Official Environmental Protection Agency Photograph

Subject: View of solidified material in a disposal cell

Location: Prairie, Monroe County, Mississippi

TDD#: 04-9010-0049
Date/Time: 20 August 1991/1100 hours
Photographer: Ayon Walters
Witness: Warren Dixon
Film: 35 mm / 100 ASA
Location of Negative: Region 41 - Memphis TAT Office

17 4 0028



PHOTO #47

Official Environmental Protection Agency Photograph

Subject: View of the solidification activities

Location: Prairie, Monroe County, Mississippi

TDD#: 04-9010-0049
Date/Time: 20 August 1991/1130 hours
Photographer: Ayon Walters
Witness: Warren Dixon
Film: 35 mm / 100 ASA
Location of Negative: Region 41 - Memphis TAT Office



PHOTO #48

Official Environmental Protection Agency Photograph

Subject: Disc utilized to size down rejected material

Location: Prairie, Monroe County, Mississippi

TDD#: 04-9010-0049
Date/Time: 21 August 1991/1100 hours
Photographer: Ayon Walters
Witness: Warren Dixon
Film: 35 mm / 100 ASA
Location of Negative: Region 41 - Memphis TAT Office




PHOTO #49

Official Environmental Protection Agency Photograph

Subject: Panoramic view of the grading and dressing activities of the site

Location: Prairie, Monroe County, Mississippi

TDD#: 04-9010-0049
Date/Time: 10 October 1991/1030 hours
Photographer: Eddy Bouzeid
Witness: Tom Kemp
Film: 35 mm / 100 ASA
Location of Negative: Region 41 - Memphis TAT Office

17 4 0031



PHOTO #43

Official Environmental Protection Agency Photograph

Subject: View of the screened material

Location: Prairie, Monroe County, Mississippi

TDD#: 04-9010-0049

Date/Time: 19 August 1991/1400 hours

Photographer: Ayon Walters

Witness: Warren Dixon

Film: 35 mm / 100 ASA

Location of Negative: Region 41 - Memphis TAT Office

17 4 0032